



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2209		Chilham	ROAD

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	85	

Comments:

SMOKE TEST PHOTOS



Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0008.JPG

Image Status: Image found and displayed.



Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0010.JPG

Image Status: Image found and displayed.




Photo No: 22

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\Retakes\UTID120-A5_2005_0519Image022.JPG


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2209		Chilham	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
---------------------	--------------	------------------	--------------	------------------

Sector:	2=Private	Drainage Area:	0
----------------	-----------	-----------------------	---

Comments: NA for drainage

SMOKE TEST PHOTOS



Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0009.JPG

Image Status: Image found and displayed.



Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2207		Chilham	ROAD

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	200	

Comments:

SMOKE TEST PHOTOS




Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0011.JPG

Image Status: Image found and displayed.



Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	8	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2207		Chilham	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
---------------------	--------------	------------------	--------------	------------------

Sector:	2=Private	Drainage Area:	200
----------------	-----------	-----------------------	-----

Comments:

SMOKE TEST PHOTOS



Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0012.JPG

Image Status: Image found and displayed.



Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	9	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2201		Chilham	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
---------------------	--------------	------------------	--------------	------------------

Sector:	2=Private	Drainage Area:	0
----------------	-----------	-----------------------	---

Comments: NA for drainage

SMOKE TEST PHOTOS



Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0014.JPG

Image Status: Image found and displayed.



Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0015.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2210		Chilham	ROAD

Source Type:	01= Main Sewer	Location:	11=Field	Severity:
Sector:	1=Public	Drainage Area:	100	

Comments: 30ft. east of mh 0691269/150 ft. north in woods

SMOKE TEST PHOTOS



Photo No: 1

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0001.jpg

Image Status: Image found and displayed.



Photo No: 3

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0003.jpg

Image Status: Image found and displayed.



Photo No: 2

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0002.jpg


Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2210		Chilham	ROAD

Source Type:	01= Main Sewer	Location:	11=Field	Severity:
Sector:	1=Public	Drainage Area:	25	

Comments: 50ft. north of mh 0691269 @ creek

SMOKE TEST PHOTOS



Photo No: 4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0004.JPG

Image Status: Image found and displayed.



Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0005.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2210		Chilham	ROAD

Source Type:	01= Main Sewer	Location:	11=Field	Severity:
Sector:	1=Public	Drainage Area:	50	

Comments: 100ft. north of mh 0691269

SMOKE TEST PHOTOS



Photo No: 6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0006.JPG

Image Status: Image found and displayed.



Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0007.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:	
2210		Chilham	ROAD	
Source Type:	01= Main Sewer	Location:	11=Field	Severity:
Sector:	1=Public	Drainage Area:	300	
Comments:	25 ft. East of creek/50 ft. East of mh 0691270			

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR02
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5724		Uffington	ROAD

Source Type:	01= Main Sewer	Location:	11=Field	Severity:
Sector:	1=Public	Drainage Area:	500	

Comments: 50ft.east of mh 0691272 @ creek

SMOKE TEST PHOTOS



Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0009.JPG

Image Status: Image found and displayed.



Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR02
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5724		Uffington	ROAD

Source Type:	12= MH Frame Seal	Location:	11=Field	Severity:
Sector:	1=Public	Drainage Area:	100	

Comments: mh frame 0691272

SMOKE TEST PHOTOS



Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0011.JPG

Image Status: Image found and displayed.



Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR01
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	Y
Defect No:	7	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2114		Webb	LANE

Source Type:	16= Storm Ditch	Location:	11=Field	Severity:
---------------------	-----------------	------------------	----------	------------------

Sector:	1=Public	Drainage Area:	10000
----------------	----------	-----------------------	-------

Comments: 25ft. West of mh 0691311

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	120	Date:	9/3/2004	MeterBasin:	01_WR10
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	8	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5800		Cross Country	Blvd

Source Type:	12= MH Frame Seal	Location:	11=Field	Severity:
Sector:	1=Public	Drainage Area:	25	

Comments: mh on Cross Country 0691310

SMOKE TEST PHOTOS



Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0014.JPG

Image Status: Image found and displayed.



Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_B\B_2004_0903Image0015.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 120

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\120.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	121	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2204		South	ROAD

Source Type:	18= Other	Location:	12=Alley	Severity:
Sector:	1=Public	Drainage Area:	10	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 46

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0046.JPG

Image Status: Image found and displayed.



Photo No: 47

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0047.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 121

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\121.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	121	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2215		Sulgrave	AVE

Source Type:	04= Cleanout	Location:	8=Yard-Back	Severity:
Sector:	2=Private	Drainage Area:	200	

Comments:

SMOKE TEST PHOTOS



Photo No: 48

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0048.JPG

Image Status: Image found and displayed.



Photo No: 49

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0049.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 121

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\121.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	121	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2211		Sulgrave	AVE

Source Type:	18= Other	Location:	8=Yard-Back	Severity:
Sector:	2=Private	Drainage Area:	100	

Comments: hole in ground

SMOKE TEST PHOTOS



Photo No: 50

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0050.JPG

Image Status: Image found and displayed.



Photo No: 51

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0051.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 121

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\121.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	121	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2211		Sulgrave	AVE

Source Type:	18= Other	Location:	8=Yard-Back	Severity:
Sector:	2=Private	Drainage Area:	200	

Comments:

SMOKE TEST PHOTOS



Photo No: 56

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0056.JPG

Image Status: Image found and displayed.



Photo No: 51

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0051.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 121

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\121.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	121	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2211		Sulgrave	AVE

Source Type:	18= Other	Location:	4=Driveway	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments: crack in driveway

SMOKE TEST PHOTOS




Photo No: 53

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0053.JPG

Image Status: Image found and displayed.



Photo No: 51

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0051.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 121

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\121.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	121	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2207		Sulgrave	AVE

Source Type:	18= Other	Location:	8=Yard-Back	Severity:
---------------------	-----------	------------------	-------------	------------------

Sector:	2=Private	Drainage Area:	50
----------------	-----------	-----------------------	----

Comments: hole

SMOKE TEST PHOTOS



Photo No: 52

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0052.JPG

Image Status: Image found and displayed.



Photo No: 54

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0054.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 121

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\121.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	121	Date:	9/3/2004	MeterBasin:	01_WR11
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2211		Sulgrave	AVE

Source Type:	18= Other	Location:	4=Driveway	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments: hole

SMOKE TEST PHOTOS



Photo No: 55

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0055.JPG

Image Status: Image found and displayed.



Photo No: 51

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0903-2004\T-1\PLAYER_A\A_2004_0903Image0051.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 121

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\121.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.